

**Crow Lane Landfill
Complaint Response Report**

ver. 08/09

Date: <u>9/4/09</u>		Time of Complaint: <u>8:55 AM</u>	
Complainant		Response	
Name: <u>Ron Klodenski</u>		Time: <u>9:02 AM</u>	
Address: <u>18 Wildwood Dr</u>		By Name: <u>Pete L. Harris</u>	
Odor	YES <input type="radio"/> NO <input checked="" type="radio"/> (circle one)		
Other: _____	Initial: <u>PH</u>		

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Side of house	0.001	0.000	0.001	0.001	No odor detected.

Weather Conditions at time of response: _____

Wind: Direction (From) SW S Speed: 0-2

Was Perimeter Landfill Survey Performed following the complaint? YES ☐ NO ☒ (circle one)

Crow Lane Landfill
Complaint Response Report

Date: <u>9-3-09</u>	Time of Complaint: <u>2:48 PM</u>
Complainant Name: <u>Michael Freye</u>	Response Time: <u>3:00 PM</u>
Address: <u>5 Wilson Way</u>	By Name: <u>Megan Thibeault</u>
Odor: <input checked="" type="radio"/> YES <input type="radio"/> NO (circle one)	
Other: _____	Initial: <u>M.T.</u>

Were odors detected during the response? No

Odor Intensity (1-5 scale) N/A Odor Duration: N/A

Odor Description/Type N/A

Location	H2S Readings During Response				Comments
Driveway	.000	.000	.000	.000	

Weather Conditions at time of response: Clear

Wind: Direction (From) SE Speed: 1 mph

Was Perimeter Landfill Survey Performed following the complaint? YES ☐ NO ☒
(circle one)

**Crow Lane Landfill
Complaint Response Report**

ver. 08/09

Date: <u>09/02/2009</u>		Time of Complaint: <u>0930 (SHOW PERSONAL NOTIFIED)</u>	
Complainant		Response	
Name: <u>ALBIA, FROY</u>		Time: <u>0950 @ LOCATION</u>	
Address <u>5 WILSON WAY</u>		By Name: <u>BOB SHORT</u>	
Odor	<u>YES</u> <u>NO</u> (circle one)		
Other: <u>H/S DETECTED BY OWNERS</u>		Initial: <u>BS</u>	
<u>BARLUM 10 AM 0600-0830</u>			

Were odors detected during the response? NO

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
DRIVE WAY	0.001	0.000			NO ODORS DETECTED @ THIS TIME
Street	0.000	0.000			

Weather Conditions at time of response: SUN 75°F RH 60% BAR 30.26"

Wind: Direction (From) CALM TO 1 MPH Speed: _____
OUT OF SOUTH

Was Perimeter Landfill Survey Performed following the complaint? YES NO
(circle one)

Crow Lane Landfill
Complaint Response Report

ver. 08/09

Date: <u>9/2/2009</u>	Time of Complaint: <u>0930 (STAFF PERSONNEL NOTIFIED)</u>
Complainant Name: <u>KIM JACKSON</u>	Response Time: <u>0930 - CALL BACK LEFT MESSAGE</u>
Address: <u>3 COURT FARM LANE</u>	By Name: <u>BEN SHORT</u>
Odor YES NO (circle one)	Initial: <u>(BS)</u>
Other: <u>NA</u>	

Were odors detected during the response? _____

Odor Intensity (1-5 scale) _____ Odor Duration: _____

Odor Description/Type: _____

Location	H2S Readings During Response				Comments

Weather Conditions at time of response: _____

Wind: Direction (From) _____ Speed: _____

Was Perimeter Landfill Survey Performed following the complaint? YES NO
(circle one)

Crow Lane Landfill
Complaint Response Report

ver. 08/09

Date: <u>8/31/09</u>	Time of Complaint: <u>8:06</u>
Complainant Name: <u>Mary Wolf</u>	Response Time: <u>8:55 AM</u>
Address <u>16 Zabotnik</u> <u>Hamburg port</u>	By Name: <u>Peter Wilansky</u>
Odor <input checked="" type="radio"/> YES <input type="radio"/> NO (circle one)	Initial: <u>PP</u>
Other: _____	

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
NW corner of house	0.000	0.000			
NE corner of house	0.000	0.000			
Back door of house	0.000	0.000			

Weather Conditions at time of response: 68°F, Sunny

Wind: Direction (From) NW Speed: 0-2 mph

Was Perimeter Landfill Survey Performed following the complaint?

YES ☐ ☒ NO
(circle one)

**Crow Lane Landfill
Complaint Response Report**

ver. 08/09

Date: <u>8/31/09</u>		Time of Complaint: <u>8:00 AM</u>	
Complainant		Response	
Name: <u>Bill Woodbury</u>		Time: <u>8:28 AM</u>	
Address: <u>Between Crow Lane and Colton Dr.</u>		By Name: <u>Peter Williams</u>	
Odor	YES	<input checked="" type="radio"/> NO	(circle one)
Other:			Initial: <u>PP</u>

Were odors detected during the response? NO

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Low st / Crow Lane	0.002	0.000			
Low st / Klindencare	0.000	0.000			
Low st / Colton	0.002	0.001			

Weather Conditions at time of response: 68°F, sunny slight wind NW

Wind: Direction (From) NW Speed: 1-2 mph

Was Perimeter Landfill Survey Performed following the complaint? YES ☒ NO (circle one)

**Crow Lane Landfill
Complaint Response Report**

ver. 08/09

Date: <u>8/31/09</u>		Time of Complaint: <u>9:14 Am</u>	
Complainant		Response	
Name: <u>Ron Klodenski</u>		Time: <u>10:23 Am</u>	
Address <u>18 Wildwood Dr</u>		By Name: <u>Peter Indaric</u>	
Odor YES <u>NO</u> (circle one)		Other: _____ Initial: <u>PI</u>	

Were odors detected during the response? NO

Odor Intensity (1-5 scale) ~~1~~ 1 Odor Duration: ~~10:24 Am~~

Odor Description/Type: ~~H₂S~~ H₂S & burnt smell

Location	H2S Readings During Response				Comments
Front of property	0.001	0.000	0.000		Ron, walking in area of 15 Wildwood, noted odor, H ₂ S in addition of burnt smell.
15 Wildwood Dr	0.000	0.001	0.002	0.010	
	0.008	0.033	0.054	0.016	
	0.015	0.019	0.011		

Weather Conditions at time of response: 71° F, Sunny

Wind: Direction (From) W Speed: 0-5 mph

Was Perimeter Landfill Survey Performed following the complaint? YES NO
(circle one)